

Re-Code for Dazzle Headlights (LED Adaptive Headlights like EU-Spec):

Change FA (VO) to Remove 5AP & 8S4 from VO

VO Code FEM_BODY Module

Read FA(VO)→Activate FA(VO)→Read SVT→Right-Click ECU & Select Code

VO Code KAFAS2 Module

Read FA(VO)→Activate FA(VO)→Read SVT→Right-Click ECU & Select Code

Now Proceed to code FEM_BODY or KAFAS2 Modules ... or re-code if coding was already present

Re-Code for Enhanced Bluetooth:

Change FA (VO) to Remove 6NH from VO & Add 6NS to VO

VO Code HU_NBT

Read FA(VO)→Activate FA(VO)→Read SVT→Right-Click ECU & Select Code

Now Proceed to code HU_NBT Module ... or re-code if coding was already present

ACSM:

Disable Welcome 3 Gongs:

3000 → Initialwarnung_GWF_IW = nicht_aktiv

Turn Off Seat-Belt Reminder Chimes:

3000 → SeatBeltReminder_SBR_Fahrer = nicht_aktiv

3000 → SeatBeltReminder_SBR_Beifahrer = nicht_aktiv

ASD Module:

Disable Active Sound Design

3000→ Funktionen-Baureihe → set to: F021

FEM_BODY Module:

Start Car by pushing button (hold clutch/brake not needed)

3020→TCM_STARTLOCK_BRAKE set to: nicht_aktiv

3020→TCM_STARTLOCK_CLUTCH set to: nicht_aktiv

3020→TCM_STARTLOCK_DRIVINGREADINESS set to: nicht_aktiv

Increase Angel Eyes Brightness to 100%

3062 → MAPPING_STANDL_V_L_PWM_LEVEL_1 = 100%

3062→ MAPPING_STANDL_V_R_PWM_LEVEL_1 = 100%

3062 → MAPPING_PARKL_V_L_PWM_1_LEFT = 100%

3062→ MAPPING_PARKL_V_L_PWM_2_RIGHT = 100%

Close windows, sunroof & mirror from key fob:

3053 → KOMFORTSCHLIESSUNG_FB = aktiv 00
3053 → KOMFORT_SCHLIESSEN → WERTE = 00 (Mirror Fold Delay = 0 sec)
3110 → ASP_BEIKLAPPEN = aktiv (werte=01)
3110 → ASP_BEIKLAPPEN_BEI_KOMFORTSCHLIESSEN = (werte=01)
3110 → ASP_AUSKLAPPEN_NACH_KOMFORTSCHLIESSEN = (werte=01)

Change Mirror Un-Fold Automatically at XX Speed (Binary value in Werte):

3110 → ASP_GESCHWINDIGKEIT_AUTO_AUSKLAPPEN → werte=14 (12Mph)

Turn off MMI when door is opened:

3020 → TCM_LOGIC_R_OFF_DOOR set to: aktiv

Auto Start/Stop Default OFF:

3023 → TCM_MSA_DEFAULT_OFF set to: aktiv

Auto Start/Stop Remember Last Setting:

3023 → TCM_MSA_MEMORY set to: aktiv

Unlock Door on Engine OFF (1 pull):

3040 → CLM_UNLOCK_KL15OFF_AFTER_PIA_AUTO_LOCK set to: aktiv

Turn off window roll-up door interrupt:

3050 → FH_TUERAUF_STOP_MAUT set to: nicht_aktiv

Change Triple-Blink Count to another Value:

3060 → BLINKZYKLEN_ANZAHL_TIPP – Werte = # blinks minus 1
(ie. 4 blinks = werte=3)

Turn on Brake Force Flashing with Hard Braking:

3060 → ESS_AKTIVIERBARER_AUSGANG = bremslicht blinkend

Turn off Amber Side Markers next to Headlight:

3063 → MAPPING_SIDEMARKER_L_OUTPUT = OFF

3063 → MAPPING_SIDEMARKER_R_OUTPUT = OFF

Turn on Fog Lights with Welcome Lights:

3063 → MAPPING_NEBELSCHW_L_PART_OF_WL = hard on

3063 → MAPPING_NEBELSCHW_R_PART_OF_WL = hard on

Tilt Passenger Mirror farther down when in reverse

3110 → ASP_BORDSTEINAUTOMATIK_DELTA set to: werte=4B

Fog Lights stay on w/ High Beams

3060 → NSW_AUS_BEI_FL set to nicht_aktiv – werte=00

Ambiance Lighting controlled independent from Dimmer Switch
3070 → AMBIENTE_NACHFUEHRUNG set to: nicht_aktiv

Enable Illumination of Exterior Door Handle LEDs when in Reverse
3070→OVT_BEI_REUCKFAHRLICHT set to: aktiv

High-Beam Assistant – Auto-On:
3060→FLA_AKTIVIERUNG set to: werte=02
3073→C_HBA_ENA set to: F030_enable=01

Disable Headlight Washers
3080 → WW_SCHEINWERFERREININUNG set to: nicht_aktiv

Auto Light Sensitivity Increase
3130→RLS_DEF_FLC_SCHWELLWERT_SATZ set to: option below
3130→RLS_FLC_SCHWELLWERT_SATZ set to: option below
Options:
normal = mornal
empfindlich = sensitive
sehr_empfindlich = very sensitive
unempfindlich = insensitive

HU_NBT Module:

High-Beam Assistant – Auto-On
3000→HIGH_BEAM_ASSISTANT set to: aktiv – werte=01

Set cell phone ringer as primary
3003→INBAND_RINGING set to: aktiv – werte=01

Disable Auto-Locking of Doors once begin driving
3000→DOOR_LOCK_AFTER_DRIVING_AWAY set to: nicht_aktiv

Enable ///M LapTmer
3000 → M_LAPTIMER set to: aktiv

Disable Active Sound Design
3000 → ASD_SOUND_OFF set to: aktiv

Enable Active Sound Design Configuration Menu
3000 → ASD_CONFIGURATION set to: aktiv
3000 → ASD_SOUND_4 set to: aktiv

Enable Turn Signals in HUD
3001→HUD_TURNSIGNAL set to: aktiv

Change Navi Voice to British English	
3000→LANGUAGE_ENGLISH_UK	set to: master
3000→LANGUAGE_ENGLISH_US	set to: nicht_aktiv
Navi Trip-Import	
3000→NAVI_TRIP_IMPORT	set to: aktiv
Enable Video Files from USB	
3000→ENT_CODEC_XVID	set to: aktiv
3000→ENT_CODEC_XVCD	set to: aktiv
3000→ENT_CODEC_OGG	set to: aktiv
DVD-in-Motion activated:	
3000 → SPEEDLOCK_X_KMH_MAX	werte = FF
3000 → SPEEDLOCK_X_KMH_MIN	werte = FF
3000 → VIDEO_HANDBRAKE	set to: nicht_aktiv
3000 → VIDEO_FRONT_LOCKED	set to: nicht_aktiv
3000 → VIDEO_SPEEDLOCK_CONDITION	set to: none=00
Remove Legal Disclaimers:	
3001 → LEGAL_DISCLAIMER_TIME	set to: kein_ld
3001 → MACRO_CAM_LEGALDISCLAIMER	set to: kein_ld
Display Tire Pressure & Temperaure in Vehicle Info:	
3001 → RDC_SAFETY	set to: aktiv 01
Add Weatherband Radio to sources:	
3002 → RADIO_WEATHERBAND	set to: aktiv 01
Enable the function of saving video files to NBT Hard Drive for play later	
3000 → ENT_MC_VIDEO_SUPPORT	set to: aktiv
Disable Office Function Speed Lock-Out	
3000→ OFFICE_MESSAGES_SPEEDLOCK_CONDITION	set to: nicht_aktiv
Enable Full Text Lines in Office While Driving	
3003 → PIM_DRIVING_TEXT_LENGTH	set to: whole text_07
Disable Audible Chirp/Beep When Locking Car	
3000 → ACOUSTICAL_LOCK_CONFIRM	set to: nicht_aktiv
Enable Speeach Input for E-Mail or SMS	
3003 → SPEECH_2_TEXT	set to: aktiv
Enable Time-Stamp Display for Call Log	
3003 → TIMESTAMP_DISPLAY	set to: aktiv

Add GPS Current Location to Navi Menu Items

3000→NAVI_POSITION_MENU set to: aktiv

Enable IPCE Web Server @ 172.16.222.1

3000→IPCE_WEBSERVER set to: aktiv

Enable WiFi Hot-Spot

(Need to install a DLNA/UPnP media sharing server on your laptop or phone to be able to use this)

3000→ENT_MC_WLAN_STREAM_DMP_COVERART set to: aktiv
3000→ENT_MC_WLAN_STREAM_DMP_VIDEO set to: aktiv
3000→ENT_MC_WLAN_STREAM_DMP set to: aktiv
3003→WLAN_STATUS set to: aktiv
3003→WLAN_MODUS set to: ap
3003→WLAN_SIGNAL_STRENGTH set to: outdoor
3003→WLAN_CHANNEL set to: channel_1 -14

Enable Developer Menu

3000 → ENTWICKLER_MENUE set to: aktiv 01

IHKA Module:

A/C System Remembers Last Setting

3003→MEMORY_OFF set to aktiv-werte=01

Always Remember Air ReCirculating

3003→MEMORY_UMLUFT set to: aktiv

KAFAS2 Module:

High-Beam Assistant – Auto-On

3050→FLA_ON_OFF set to: aktiv – werte=01

KOMBI Module:

Show Digital Speed in MPH in Cluster

3000→BC_DIGITAL_V set to: aktiv-werte=01

Show Turn Signals in HUD

3008→HUD_PIA_BLINKER set to: aktiv
3000→HUD_BLINKER_ENABLE set to: aktiv

Enable GPS-Sync for Clock

3000→GPS_UHR set to: aktiv

Disable HUD Startup Animation
3008→HUD_STARTUP_TIME

Werte=00

TRSVC Module:

Enable Side-View Cameras at all Speeds
3000→SV_Activate_Speed_Limit
3000→SV_Deactivate_Speed

Werte=FF

Werte=FF